

# Inspection Photos

API: 055-06212

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/7/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06212 | Date: 6/7/2022

## Inspection Photos



**Photo 1.** Facing west toward the access road which was not reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/7/2022



## Inspection Photos



**Photo 2.** Facing west toward the location. The location was never recontoured and reclaimed. The surface owner is using the location for a storage area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/7/2022



## Inspection Photos



**Photo 3.** There are noxious weeds at the location which include Cheat grass, Red stem filaree, Field bind weed, and Jointed Goat grass.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/7/2022



## Inspection Photos



**Photo 4.** Facing northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06212 | Date: 6/7/2022