

Inspection Photos

API: 055-06194

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/7/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06194 | Date: 6/7/2022

Inspection Photos



Photo 1. Facing southwest at the location. The desirable vegetation has not re-established and there are noxious weeds including Red stem filaree, Scotch thistle, and Mullein.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06194 | Date: 6/7/2022

Inspection Photos



Photo 2. Facing west at the location.



Inspection Photos



Photo 3. There are areas of the location that are bare of vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06194 | Date: 6/7/2022

Inspection Photos



Photo 4. Facing northwest at the east side of the location. The desirable vegetation has not re-established and there are noxious weeds including Red stem filaree, Field Mullein, and Scotch thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06194 | Date: 6/7/2022

Inspection Photos



Photo 5. Facing southeast toward the location. The desirable vegetation has not re-established at the location and there are noxious weeds including Red stem filaree, Mullein, and Scotch thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06194 | Date: 6/7/2022