

Inspection Photos  
Location Name: Brozovick Unit 1  
Location ID: 317952



Photo 1 WH sign.

Photo 2 Stained soil around the WH.

**Inspection Photos**  
**Location Name: Brozovick Unit 1**  
**Location ID: 317952**



**Photo 3 Pump Jack.**



**Photo 4 Ancillary equip..**

**Inspection Photos**  
**Location Name: Brozovick Unit 1**  
**Location ID: 317952**



**Photo 5 stained soil just east of the WH.**

**Photo 6 Flow line manifold.**



**Inspection Photos**  
**Location Name: Brozovick Unit 1**  
**Location ID: 317952**



**Photo 7 stained soil by flow line manifold .**

**Photo 8 stained soil by flow line manifold.**

**Inspection Photos**  
**Location Name: Brozovick Unit 1**  
**Location ID: 317952**



**Photo 9 unmarked flow line no LOTO.**

**Photo 10 unmarked flow line no LOTO, looks to have about 85 PSI on it.**