

Inspection Photos
Location Name: Clifford Causey #10
Location ID: 319632



Photo #1 Tanks.



Photo #2 Separator, ECD, Propane tank.

Inspection Photos
Location Name: Clifford Causey #10
Location ID: 319632



Photo #3 Produced water tanks and oil spill.



Photo #4 Crude oil.



Inspection Photos
Location Name: Clifford Causey #10
Location ID: 319632



Photo #5 crude oil.



Photo #6 crude oil.

Inspection Photos
Location Name: Clifford Causey #10
Location ID: 319632



Photo #7 pit #1.



Photo #8 pit 1 & 2.

Inspection Photos
Location Name: Clifford Causey #10
Location ID: 319632



Photo #9 trash around pit.



Photo #10 Trash around pit.



Inspection Photos
Location Name: Clifford Causey #10
Location ID: 319632



Photo #11 Pit #2.



Photo #12 Pump Jack.

Inspection Photos
Location Name: Clifford Causey #10
Location ID: 319632



Photo #13 well head packing leaking.



Photo #14 bucket storage around pump jack.



Inspection Photos
Location Name: Clifford Causeway #10
Location ID: 319632



Photo #15 trash around location.



Photo #16 stained soil around load out bucket .



Inspection Photos
Location Name: Clifford Causey #10
Location ID: 319632



Photo #17 no bull plug on load out line.



Photo #18 stained soil around crud tanks.

Inspection Photos
Location Name: Clifford Causey #10
Location ID: 319632



Photo # 19 stained soil.



Photo #20 stained soil.