

Inspection Photos

Location Name: Perkins-Thornburg 1

Location ID: 320023



Pic 1 wellhead / pumpjack



Pic 2 gas meter run, separators

Inspection Photos
Location Name: Perkins-Thornburg 1
Location ID: 320023



Pic 3 separator mechanical issue/stained soil



Pic 4 water tank with no containment

Inspection Photos
Location Name: Perkins-Thornburg 1
Location ID: 320023



Pic 5 tanks