

Inspection Photos

Location Name: Bowen Amoco 44-08

Location ID: 320061



Pic 1 tanks



Pic 2 separator




Inspection Photos

Location Name: Bowen Amoco 44-08

Location ID: 320061

Jun 8, 2022 at 2:55:09 PM
39.798026,-104.342017
Adams County
COGCC



Pic 3 wellhead / pump jack

Jun 8, 2022 at 2:56:40 PM
39.798206,-104.342118
Adams County
COGCC



Pic 4 stained soil/trash inside motor house

Inspection Photos

Location Name: Bowen Amoco 44-08

Location ID: 320061



Pic 5 stained soil / trash inside motor house



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources