

Inspection Photos
Location Name: Saulcy-Gentry #1
Location ID: 307171



Production facility



Wellhead

Inspection Photos
Location Name: Saulcy-Gentry #1
Location ID: 307171



Master valve leak and stained soil