

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4NWSE

Location ID: 334795



Photo #6890 from entrance to location.



Photo #6891 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4NWSE

Location ID: 334795



Photo #6892 from entrance to location.



Photo #6894 Loadline open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4NWSE

Location ID: 334795



Photo #6895 Loadline open ended.



Photo #6896 Vent pipe on tank open ended.