

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3SWNW

Location ID: 334807



Photo #6902 from entrance to location.



Photo #6903 Vent pipes on tank open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3SWNW

Location ID: 334807



Network: Jun 13, 2022 at 1:30:40 PM MD
Local: Jun 13, 2022 at 1:30:40 PM MD

Photo #6904 Loadline open ended.