


Inspection Photos

Location Name: Southern Ute Allottee BC 2
Location ID: 326566




IMG 01
Well sign



IMG 02
Site Overview



IMG 03
Wellhead




IMG 04
Impacted material around wellhead





IMG 05

Lube oil on wellhead, impacting surface material



IMG 06

Unused equipment and debris



IMG 07
Unmarked rig anchor



IMG 08
Unused post with concrete base



IMG 09
Fill dirt pile