

# Inspection Photos and Issue Report

6/14/2022

Operator: PRE RESOURCES INC - 10241

Location ID: 322302

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: PRE RESOURCES INC - 10241

Location ID: 322302



June 14, 2022  
39.59196285N 108.89721853W



June 14, 2022  
39.59196645N 108.89721784W

**Photo 1:** Photos taken from the north end of the Location, facing southeast / south. Photos provides an overview of the Location; Location has not been reclaimed in accordance with Rule 1004.a: Location and access road have not been decompacted, recontoured and reclaimed- Cut/fill slope remains evident, secondary containment berms remain evident, gravel has not been removed; surface equipment (pipe) remaining on northwest end of the Location; Vegetation on Location is predominantly Undesirable and Noxious Plant Species including, but not limited to, Field Bindweed, Redstem filaree, Hoary Cress, etc...

Inspection Photos  
Operator Name: PRE RESOURCES INC - 10241  
Location ID: 322302



**Photo 2:** Photos show vegetation on Location is predominantly Undesirable and Noxious Plant Species including, but not limited to, Field Bindweed, Redstem filaree, Hoary Cress, etc... Weed management inadequate on the Location, and is required until site receives a passing final reclamation inspection.

Inspection Photos  
Operator Name: PRE RESOURCES INC - 10241  
Location ID: 322302



**Photo 3:** Photo shows cut slope remaining; location has not been recontoured/regraded.

Inspection Photos  
Operator Name: PRE RESOURCES INC - 10241  
Location ID: 322302



**Photo 4:** Photo left shows access road has not been reclaimed. Photo right shows pipe equipment remaining t on the Location

Inspection Photos  
Operator Name: PRE RESOURCES INC - 10241  
Location ID: 322302



**Photo 5:** Photo shows Hoary cress established along the un-reclaimed access road.