

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403082534

Date Received:
06/16/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693904398

Inspection Date: 04/19/2022

FIR Submit Date: 04/20/2022

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306807

Location Name: SOUTHERN UTE GAS UNIT Number: 19NENE County: LA PLATA
Q-N33N7W

Qtrqtr: NENE Sec: 19 Twp: 33N Range: 7W Meridian: N

Latitude: 37.094209 Longitude: -107.645331

FACILITY - API Number: 05-067-00 Facility ID: 267795

Facility Name: SOUTHERN UTE Q Number: 2

Qtrqtr: NENE Sec: 19 Twp: 33N Range: 7W Meridian: N

Latitude: 37.094209 Longitude: -107.645331

CORRECTIVE ACTIONS:

1 CA# 161156

Corrective Action: -Stormwater controls need to be installed and maintained within the southeastern and southwestern project area where headcutting erosion and down-cutting is occurring, by 5/20/2022.

Date: 05/20/2022

Response: CA COMPLETED

Date of Completion: 05/23/2022

Operator Comment: Rock runout installed on southwest corner of locations. rock runout and waddles installed on southeast side of location.

COGCC Decision: _____

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: CA Completed. See attached photos.

--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: _____

Title: Permitting Specialist I

Date: 6/16/2022 4:24:05 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403082537	SU Q2, CA Completion Photos
-----------	-----------------------------

Total Attach: 1 Files