



Overview of WC27 Location ID 314510. Fence panels completely enclose excavated area.



Excavation around wellhead is clean and the slope of the pit is sufficiently gentle to allow for wildlife egress.



Excavated soil has been removed from location



Power pole has been removed from location



Area was repaired and waddles were repaired or replaced to control sediment.

