

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2022

Submitted Date:

06/17/2022

Document Number:

700600392

FIELD INSPECTION FORM

 Loc ID: 309609 Inspector Name: Kosola, Jason On-Site Inspection: 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 61250
 Name of Operator: MULL DRILLING COMPANY INC
 Address: 1700 N WATERFRONT PKWY B#1200
 City: WICHITA State: KS Zip: 67206-
Findings:
 3 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Beilman, James	316-734-8108	JBeilman@mulldrilling.com	Environmental/Safety Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267113	WELL	SI	04/01/2018	ERIW	073-06304	Meteor Unit 2	EI
432414	TANK BATTERY	AC	04/04/2013		-	VICK A	EI
482362	SPILL OR RELEASE	AC	06/15/2022		-	Meteor Unit #2; fka Vick A #1-9	EI

General Comment:

This is an environmental inspection to document spill 482362.

Form 19 Initial Spill Report has already been submitted.

Operator shall ensure that impacted area inside tank battery containment is compliant with Table 915-1 before returning to service.

Inspected Facilities

Facility ID: 267113 Type: WELL API Number: 073-06304 Status: SI Insp. Status: EI

Facility ID: 432414 Type: TANK API Number: - Status: AC Insp. Status: EI

Facility ID: 482362 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Spill of crude oil and produced water into containment as a result of fire.

Corrective Action: Form 19 spill report has already been submitted. Date: _____

Reportable: YES GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700600393	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782665