

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-67S96W /2NENE

Location ID: 324152



Photo #6923 from entrance to location.

Photo #6924 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-67S96W /2NENE

Location ID: 324152



Photo #6927 Wellhead sign weathered and not legible.



Photo #6928 Vent pipe on tank open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-67S96W /2NENE

Location ID: 324152



Network: Jun 15, 2022 at 1:22:06 PM MD
Local: Jun 15, 2022 at 1:22:06 PM MD



Network: Jun 15, 2022 at 1:21:00 PM MD
Local: Jun 15, 2022 at 1:21:00 PM MD

Photo #6929 Loadline open ended.

Photo #6925 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-67S96W /2NENE

Location ID: 324152



Photo #6926 Location lacks stabilization.