

NORTH SHORE EXPLORATION AND PRODUCTION LLC

EVANS-611N93W 28SWNW

Location # 333326



Signs have address for previous operator. No Telephone number for local emergency services (911 where available) and no public road used to access the Tank battery site;

NORTH SHORE EXPLORATION AND PRODUCTION LLC
EVANS-611N93W 28SWNW
Location # 333326



No API # on well sign.
Weeds growing around wells.



No API # on well sign.

NORTH SHORE EXPLORATION AND PRODUCTION LLC
EVANS-611N93W 28SWNW
Location # 333326



Signs have address for previous operator. No Telephone number for local emergency services (911 where available) and no public road used to access the Tank battery site;

No API # on well signs.

NORTH SHORE EXPLORATION AND PRODUCTION LLC
EVANS-611N93W 28SWNW
Location # 333326



NORTH SHORE EXPLORATION AND PRODUCTION LLC
EVANS-611N93W 28SWNW
Location # 333326



**Poly methanol tanks behind meter sheds missing
NFPA label and tank capacities are weathered.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

NORTH SHORE EXPLORATION AND PRODUCTION LLC
EVANS-611N93W 28SWNW
Location # 333326



Deadman marker at tank battery has been bent over.



Deadman marker at tank battery has been bent over.

**NORTH SHORE EXPLORATION AND PRODUCTION LLC
EVANS-611N93W 28SWNW
Location # 333326**



Weeds growing inside of tank battery.



NORTH SHORE EXPLORATION AND PRODUCTION LLC
EVANS-611N93W 28SWNW
Location # 333326



Weeds growing inside separator berm.



Metal tank between separators NFPA, contents, and capacity are faded.

NORTH SHORE EXPLORATION AND PRODUCTION LLC
EVANS-611N93W 28SWNW
Location # 333326



Weeds growing inside separator berm.



Weeds growing inside separator berm.