


Inspection Photos
Location Name: Hayes 33-9 5-3 and 5-3A
Location ID: 312096




IMG 01
Well Sign



IMG 02
Site overview



IMG 03
Site overview



IMG 04
Unused equipment





IMG 05

Truck near Hayes 33-9 5-3 well



IMG 06

Unmarked rig anchor




IMG 07

Unused equipment



IMG 08

Unused equipment and debris



IMG 09

Produced water tank sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources