

Inspection Photos

API: 055-06017

Operator: OXY USA INC

Inspection Date: 6/16/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06017 | Date: 6/16/2022

Inspection Photos



Photo 1. Facing south toward the access road. There is disturbance created from the flowline excavation that needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06017 | Date: 6/16/2022

Inspection Photos



Photo 2. Facing south toward the Koscove #1 well site. The piles of sand material will need to be removed and disturbance reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06017 | Date: 6/16/2022