

# Final Reclamation Inspection

June 9, 2022

Operator: TOP OPERATING COMPANY - 39560

Location ID: 319168

Inspection Document #: 697503998

Weld County, CO

SESE Section 7 T2N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: POWELL #1  
Location ID: 319168



**Photo 1.** Google Earth aerial imagery taken on 6/10/2021. Photo illustrates the well location and access road that need to be reclaimed.



Inspection Photos  
Location Name: POWELL #1  
Location ID: 319168



**Photo 2.** Photo taken from the well location, facing North. Photo illustrates all equipment has been removed from location but final reclamation has not been completed with the evidence of some gravel, access road remains and decompaction still needing to be performed.



**Photo 3.** Photo taken from the well location, facing Northeast. See comments under Photo 1.



Inspection Photos  
Location Name: POWELL #1  
Location ID: 319168



**Photo 4.** Photo taken from the well location, facing East. See comments under Photo 1.



**Photo 5.** Photo taken from the well location, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: POWELL #1  
Location ID: 319168



**Photo 6.** Photo taken from the well location, facing South.  
Photo illustrates the access road that needs to be reclaimed.



**Photo 7.** Photo taken from a portion of the access road, facing South. See comments under Photo 6.