

Final Reclamation Inspection

June 9, 2022

Operator: TOP OPERATING COMPANY - 39560

Location ID: 331060

Inspection Document #: 697504000

Weld County, CO

NESE Section 7 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: EVANS #6
Location ID: 331060



Photo 1. Photo taken from the northern well location access road, facing South. Photo illustrates all equipment has been removed from location and final reclamation have been completed. However, there was very little establishment of desirable vegetation and mostly consisted of weedy annual vegetation.



Photo 2. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: EVANS #6
Location ID: 331060



Photo 3. Photo taken from the well location. Photo illustrates a List B Colorado noxious weed, Hoary cress.



Photo 4. Photo taken from the well location, facing Southeast. See comments under Photo 1.

Inspection Photos
Location Name: EVANS #6
Location ID: 331060



Photo 5. Photo taken from the well location, facing East. See comments under Photo 1.



Photo 6. Photo taken from the well location, facing Northeast. See comments under Photo 1.

Inspection Photos
Location Name: EVANS #6
Location ID: 331060



Photo 7. Photo taken from the well location, facing Northwest. See comments under Photo 1.



Photo 8. Reference photo taken east of the well location, facing East.

Inspection Photos
Location Name: EVANS #6
Location ID: 331060



Photo 9. Photo taken from the associated offsite tank battery location, facing Northeast. See comments under Photo 1.



Photo 10. Photo taken from the associated offsite tank battery location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: EVANS #6
Location ID: 331060



Photo 11. Aerial imagery illustrates the well location/access road in red and the associated offsite tank battery in orange.