

Inspection Photos

June 16, 2022

Operator: Robert L Bayless Producer LLC - #6720

Location ID: 313011

Location Name: Zimmerman/Chamberlin-66N91W/4SWSE

Inspection Document #: 702800363

Moffat County, CO

SWSE Section 4 T6N R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Zimmerman/Chamberlin-
66N91W /4SWSE
Location ID: 313011



Photo 1. Photo taken from the west of the Location shows storage of equipment on the Location. Photo also shows a straw wattle which was recently reinstalled.



Photo 2. Refer to Photo 1 comment.

Inspection Photos
Location Name: Zimmerman/Chamberlin-
66N91W /4SWSE
Location ID: 313011



Photo 3. Photo taken from the southwest of the pumpjack shows an absence of stained soils/gravel.



Photo 4. Photo taken from the tank battery to the east of the Location shows an absence of stained soils/gravel.

