


Inspection Photos  
Location Name: Paisley #2  
Location ID: 326675



IMG 01  
Well sign



IMG 02  
Location overview



**IMG 03**

**Lube oil is impacting surface material**