

# Inspection Photos

June 22, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 383144

Location Name: Youberg-66S94W /35SESE

Inspection Document #: 702800369

Garfield County, CO

SESE Section 35 T6N R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Youberg-66S94W /35SESE  
Location ID: 383144



**Photo 1.** Photo taken from the northwest of the Location on the access road shows an overview of the reclaimed access road and Location.



**Photo 2.** Photo taken from the north of the Location shows an overview of the reclaimed Location. Photo shows the northern portion of the Location (foreground) dominated by noxious weeds and undesirable plant species cheatgrass and Russian thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800369



Inspection Photos  
Location Name: Youberg-66S94W /35SESE  
Location ID: 383144



**Photo 3.** Photo taken from the southeast of the Location shows that establishment of desirable perennial plants is not uniform. Some areas are vegetated with native and seeded non-native perennial species (middleground), while others are dominated by noxious weeds and undesirable plant species (foreground).



**Photo 4.** Photo taken from the south of the Location shows musk thistle, a CO List B Noxious Weed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800369



Inspection Photos  
Location Name: Youberg-66S94W /35SESE  
Location ID: 383144



**Photo 5.** Photo taken from the north of the Location shows straw wattles in disrepair. Stormwater is cutting underneath the wattles and some have come unstaked. Also note, the stage of Russian thistle development for determining appropriate control methods.



**Photo 6.** Refer to photo 5 comment.



Inspection Photos  
Location Name: Youberg-66S94W /35SESE  
Location ID: 383144



**Photo 7.** Photo taken to the east of the Location shows the reference area vegetation community is dominated by pinyon and juniper with a native forb and grass understory.