

TEP  
Weinreis A  
Location # 335548



location



location



TEP  
Weinreis A  
Location # 335548



location



location



TEP  
Weinreis A  
Location # 335548



Debris



Debris



TEP  
Weinreis A  
Location # 335548



**Debris**



**Actively leaking valve on condensate tank/ staining**



TEP  
Weinreis A  
Location # 335548



Staining



Staining



TEP  
Weinreis A  
Location # 335548



**Lack of stabilization/ erosion**



**Lack of stabilization/ erosion**



TEP  
Weinreis A  
Location # 335548



**Lack of stabilization/ erosion**



**Lack of stabilization/ erosion**





TEP  
Weinreis A  
Location # 335548



**Lack of stabilization/ erosion**



**Lack of stabilization/ erosion**

