

Inspection Photos

June 22, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 323890

Location Name: Barrett-66S94W /35NESW

Inspection Document #: 702800375

Garfield County, CO

NESW Section 35 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Barrett-66S94W /35NESW
Location ID: 323890



Photo 1. Photo taken from the west shows an overview of the Location.

Inspection Photos
Location Name: Barrett-66S94W /35NESW
Location ID: 323890



Photo 2. Photo taken from the south of the Location shows southern interim areas dominated by the weedy, native shrub, rubber rabbitbrush, sagebrush, and non-native perennial grasses crested wheatgrass, smooth brome and tall wheatgrass.



Photo 3. Photo taken from the east of the Location shows eastern interim areas. Refer to additional comments under Photo 2.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800375

Inspection Photos
Location Name: Barrett-66S94W /35NESW
Location ID: 323890



Photo 4. Photo taken from the northeast of the Location shows northeastern interim areas. Refer to additional comments under Photo 2.



Photo 3. Photo taken from the northwest of the Location shows northwestern interim areas. Refer to additional comments under Photo 2. Western wheatgrass (native) is also common.