

Inspection Photos
Location Name: State Royce 1-36
Location ID: 325533



IMG 01
Well sign



IMG 02
Location overview



IMG 03

Ruts on location




IMG 04

Gas meter with no calibration record



IMG 05

Trash north of separator



IMG 06

Trash east of compressor



IMG 07

Trash on west edge of location



IMG 08

Trash on west edge of location



IMG 09

Deteriorated and unmaintained wattles



IMG 10

Deteriorated and unmaintained wattles





IMG 11

Ditch on west end of location is overtopping. Water run on is entering location

