

Inspection Photos
Location Name: Arthur Scheetz #1
Location ID: 317520



Photo 1 – Pumping Unit



Photo 2 – Wellhead

Inspection Photos
Location Name: Arthur Scheetz #1
Location ID: 317520



Photo 3 – Unused Belts

Photo 4 – Unused Rods and Tubing

Inspection Photos
Location Name: Arthur Scheetz #1
Location ID: 317520



Photo 5 – Pit

Photo 6 – Pit

Inspection Photos
Location Name: Arthur Scheetz #1
Location ID: 317520



Photo 7 – Water Tanks



Photo 8 – Heater Treater

Inspection Photos
Location Name: Arthur Scheetz #1
Location ID: 317520



Photo 9 – Crude Oil Tanks

Photo 10 – Tank Battery Sign