

Inspection Photos
Location Name: #1 Dunbar
Location ID: 305616



Photo 1 – Pumping Unit



Photo 2 – Wellhead



Inspection Photos
Location Name: #1 Dunbar
Location ID: 305616



Photo 3 – Stained Soil and Unused Tubing



Photo 4 – Stained Soil

Inspection Photos
Location Name: #1 Dunbar
Location ID: 305616



Photo 5 – Wellhead Sign



Photo 6 – Gear Box Leak

