

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC Federal /DOE 2-W-29

Location ID: 335255



Photo #6963 from entrance to location.



Photo #6964 from entrance to location.

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC Federal /DOE 2-W-29

Location ID: 335255



Photo #6965 from entrance to location.



Photo #6967 Undesirable plant species in tank containment.

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC Federal /DOE 2-W-29

Location ID: 335255




Photo #6968 Undesirable plant species in tank containment.



Photo #6969 unused equipment.

Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC Federal /DOE 2-W-29

Location ID: 335255



Photo #6970 Unused equipment.