

Final Reclamation Inspection

May 11th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 327207

Inspection Document #: 701900369

NESW Section 30 T4N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Gress 23-30
Location ID: 327207




Photo 1. 2021 aerial imagery of the well pad, tank battery, access road and reference area.
Note: the tank battery has been absorbed by the Ram Land production facility.

Inspection Photos
Location Name: Gress 23-30
Location ID: 327207




Photo 2. Left photo taken from the northern edge looking south down the access road towards the well pad. Campartiviley, right photo taken at the same orientation (north to south) taken just west of the access road. Note: Left photo shows stunted plant growth (Russian wildrye).

Inspection Photos
Location Name: Gress 23-30
Location ID: 327207



Photo 3. Overview photo of northern well pad disturbance taken at ground level from the northern disturbance edge looking south. Note: disturbance shows little plant establishment and doesn't appear consistent with adjacent reference area (see photo 5).

Inspection Photos
Location Name: Gress 23-30
Location ID: 327207



Photo 4. Overview photo of southern well pad disturbance taken at ground level from the northern disturbance edge looking south. Note: disturbance shows little plant establishment and doesn't appear consistent with adjacent reference area (see photo 5).

Inspection Photos
Location Name: Gress 23-30
Location ID: 327207



Photo 5. Reference area.

Inspection Photos
Location Name: Gress 23-30
Location ID: 327207



Photo 6. Tank battery. Note: absorbed by new Ram Land production facility. Note: no weed or erosion issues observed.