

Inspection Photos
Location Name: Carter Ute 107
Location ID: 326093



IMG 01
Well sign



IMG 02
Location overview



IMG 03

Lube oil with no spill prevention



IMG 04

Oil container with no spill prevention



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



IMG 05

Unused equipment



IMG 06

Unused equipment



IMG 07

Impacted material



IMG 08

Impacted material



IMG 09

Impacted material



IMG 10

Tank signs beginning to deteriorate



IMG 11

Flow line not in use