

Inspection Photos

API: 071-09460

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/28/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09460 | Date: 6/28/2022

Inspection Photos



Photo 1. Facing northeast toward the reclaimed access road. Perennial vegetation has re-established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09460 | Date: 6/28/2022

Inspection Photos



Photo 2. Facing northwest toward the reclaimed access road and location.



Inspection Photos



Photo 3. Facing north at the top portion of the location. There are some noxious weeds (Mullein) that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09460 | Date: 6/28/2022

Inspection Photos



Photo 4. Facing east at the top portion of the location. There are some noxious weeds (Canada thistle) that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09460 | Date: 6/28/2022

Inspection Photos



Photo 5. Facing southeast at the reclaimed location. Perennial vegetation has re-established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09460 | Date: 6/28/2022

Inspection Photos



Photo 6. Facing north at the reclaimed location. Perennial vegetation has re-established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09460 | Date: 6/28/2022