

Inspection Photos
Location Name: McCallum Unit 43
Location ID: 324603



Photo 1. Overview of location taken facing north.



Photo 2. Close up of wellhead and spill.



Inspection Photos
Location Name: McCallum Unit 43
Location ID: 324603



Photo 3. Close up of spill. Animal footprints visible in mud.



Photo 4. Close up of spill.