

**Inspection Photos**  
**Location Name: McCallum Unit 9**  
**Location ID: 324588**



**Photo 1. Overview of location taken facing south. No wellhead sign. Debris/equipment on location.**

