

Inspection Photos

July 1, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 423182

Location Name: Benzel/26-6H (F25NWB)

Inspection Document #: 702800414

Garfield County, CO

SENW Section 25 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Benzel/26-6H (F25NWB)
Location ID: 423182



Photo 1. Photo taken from the west at the Location entrance shows an overview of the northern production area.



Photo 2. Photo taken from the west at the Location entrance shows an overview of the southern production area. Photo also shows areas at the southwest of the working pad area which can be reduced and reclaimed.

Inspection Photos
Location Name: Benzel/26-6H (F25NWB)
Location ID: 423182



Photo 3. Map shows the distance from the producing wells at the northwest of the Location to the southwestern edge of the pad is approximately 140 feet. Areas at the southwest of the working pad area not necessary for production operations can be reduced and reclaimed.

Inspection Photos

Location Name: Benzel/26-6H (F25NWB)

Location ID: 423182



Photo 4. Photo taken from the east of the Location shows perennial pepperweed (CO List B Noxious Weed).



Photo 5. Photo taken from the sediment pond at the southwest of the Location shows Russian knapweed (CO List B Noxious Weed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800414

Inspection Photos
Location Name: Benzel/26-6H (F25NWB)
Location ID: 423182



Photo 6. Photo taken from the north of the Location shows the northern interim area is dominated by seeded species including Russian wildrye, intermediate wheatgrass, and tall wheatgrass (non-native perennial grasses). Some western wheatgrass (native perennial grass) is occasionally present.



Photo 7. Photo taken from the east of the Location shows the eastern interim area is dominated by seeded perennial grasses. Photo also shows an example of an area with poor perennial grass establishment colonized by Russian thistle and kochia (undesirable plant species).

Inspection Photos
Location Name: Benzel/26-6H (F25NWB)
Location ID: 423182



Photo 8. Photo taken from the north of the Location shows the adjacent reference area is dominated by cheatgrass (annual, CO List C Noxious Weed) and sparse western wheatgrass (native perennial grass).



Photo 9. Photo taken from the east of the Location shows the adjacent reference area is dominated by sagebrush, cheatgrass (annual, CO List C Noxious Weed) and sparse western wheatgrass (native perennial grass).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800414