

Inspection Photos

July 1, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 323927

Location Name: Shaefer-67S93W /12SENE

Inspection Document #: 702800418

Garfield County, CO

SENE Section 12 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Shaefer-67S93W /12SENE
Location ID: 323927



Photo 1. Photo taken from the south shows an overview of the Location.

Inspection Photos
Location Name: Shaefer-67S93W /12SENE
Location ID: 323927




Photo 2. Photo taken from the south of the Location shows an anchor and marker which must be removed per 1004 Rules.



Photo 3. Photo taken from the reclaimed area shows a buried cable which must be removed per 1004 Rules.

Inspection Photos
Location Name: Shaefer-67S93W /12SENE
Location ID: 323927



Photo 4. Photo taken from the reclaimed area shows a buried cable which must be removed per 1004 Rules.



Photo 5. Photo taken from the reclaimed area shows buried equipment which must be removed per 1004 Rules.



Inspection Photos

Location Name: Shaefer-67S93W /12SENE

Location ID: 323927



Photo 6. Photo taken from the reclaimed area shows a buried cable which must be removed per 1004 Rules.



Photo 7. Photo taken from the reclaimed area shows trash which must be removed per 1004 Rules.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800418

Inspection Photos

Location Name: Shaefer-67S93W /12SENE

Location ID: 323927



Photo 8. Photo taken from the reclaimed area shows large dense soil peds indicating a possible lack of decompaction.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800418