

Inspection Photos
Location Name: Park T-4 Pad
Facility ID: 428521



Photo #1 Removed stained soil



Photo #2 Oily Waste

Inspection Photos
Location Name: Park T-4 Pad
Facility ID: 428521



Photo #3 Stained Soil & oily waste on compressor skid



Photo #4 Stained soil



Inspection Photos
Location Name: Park T-4 Pad
Facility ID: 428521



Photo #5 Oily Waste on Compressor skid & Mechanical Conditions



Photo #6 Oily Waste on Compressor skid & Mechanical Conditions

Inspection Photos
Location Name: Park T-4 Pad
Facility ID: 428521



Photo #7 Oily Waste on Compressor skid & Mechanical Conditions



Photo #8 Oily Waste on Compressor skid & Mechanical Conditions

Inspection Photos
Location Name: Park T-4 Pad
Facility ID: 428521



Photo #9 Oily Waste on Compressor skid & Mechanical Conditions



Photo #10 Removed Unused Equipment