

# Inspection Photos

API: 017-07754

Operator: PRONGHORN OPERATING LLC

Inspection Date: 7/6/2022



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07754 | Date: 7/6/2022

## Inspection Photos



**Photo 1.** Center of the location facing north. The native vegetation has reestablished throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07754 | Date: 7/6/2022

## Inspection Photos



**Photo 2.** Center of the location facing west. The native vegetation has reestablished throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07754 | Date: 7/6/2022



## Inspection Photos



**Photo 3.** Center of the location facing south. The native vegetation has reestablished throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07754 | Date: 7/6/2022



## Inspection Photos



**Photo 4.** Center of the location facing east. The native vegetation has reestablished throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07754 | Date: 7/6/2022