

Inspection Photos

API: 017-07796

Operator: PRONGHORN OPERATING LLC

Inspection Date: 7/6/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 017-07796 | Date: 7/6/2022

Inspection Photos



Photo 1. Facing east toward the location. The crop has not uniformly established and there are area with no sign of crop growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07796 | Date: 7/6/2022

Inspection Photos



Photo 2. Facing north toward the location. The crop has not uniformly established and there are area with no sign of crop growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07796 | Date: 7/6/2022

Inspection Photos



Photo 3. Facing west toward the location. The crop has not uniformly established and there are area with no sign of crop growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07796 | Date: 7/6/2022

Inspection Photos



Photo 4. Facing south toward the location. The crop has not uniformly established and there are area with no sign of crop growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07796 | Date: 7/6/2022

Inspection Photos



Photo 5. Facing toward the surrounding undisturbed cropland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07796 | Date: 7/6/2022