

Inspection Photos  
Location Name: UPRR 42 Pan Am AF 1  
Location ID: 332876



Photo 1 WH sign.

Photo 2 WH

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am AF 1**  
**Location ID: 332876**



**Photo 3 TB sign.**

**Photo 4 TB**

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am AF 1**  
**Location ID: 332876**



**Photo 5 weeds growing around WH and PJ.**

**Photo 6 ancillary equip.**

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am AF 1**  
**Location ID: 332876**



**Photo 7 weeds growing around TB location.**

**Photo 8 Stained soil by the Gas Meter Run.**

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am AF 1**  
**Location ID: 332876**



**Photo 9 Stained soil by crude oil load out line.**

**Photo 10 Stained soil by the crude oil tank valve .**

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am AF 1**  
**Location ID: 332876**



**Photo 11 HHS.**