

**COLORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT**



1120 Lincoln
Denver, CO 80203
(303)894-2100

NOTICE OF UNSATISFACTORY INSPECTION
 NOTICE OF SATISFACTORY INSPECTION

API No. 05- 063 - 6246	LEASE NAME: COLMENO 12-30 #1
LOCATION: SWNW3D-115-50W	OPERATOR: UPR
DATE: 8-23-96	INSPECTOR: R. Van Sickle
Insp. Type: PR	Insp. Status: PR
PA: Y N	Pass/Fail: (P) F
	Viol.: Y (N)
	NOV: Y (N)

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	✓	
Pits (Reserve/Production) (Rule 902, 903, 904)	None.	
Fences (Rule 604.C.(3), 1003.A)	None.	
Tank Battery Equipment (Rule 604)	Pmpg unit, 2-400's, sep, 2 vent, H-TS, GMR, 400 BBL water tk.	✓
Fire Walls/Berms/Dikes (Rule 604)	OK	
General Housekeeping (Rule 603.G)	OK	
Spills (Oil/Water) (Rule 908)	None.	
Bradenhead (Rule 207)	—	
Drilling Well/Workover (Rule 315)	—	
Surface Rehabilitation (Rule 317)	—	
Miscellaneous	—	

CORRECTIVE ACTION REQUIRED: None.

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.