

Inspection Photos

API: 017-07716

Operator: MID-CON ENERGY OPERATING

Inspection Date: 7/7/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 017-07716 | Date: 7/7/2022

Inspection Photos



Photo 1. Facing southeast toward the location. There is a perimeter fence around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07716 | Date: 7/7/2022

Inspection Photos



Photo 2. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07716 | Date: 7/7/2022

Inspection Photos




Photo 3. Facing north at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07716 | Date: 7/7/2022

Inspection Photos



Photo 4. Facing south at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07716 | Date: 7/7/2022