

Inspection Photos  
Location Name: Knight D 1  
Location ID: 326331



IMG 01  
Well sign



IMG 02  
Location overview



**IMG 03**  
**Bales of hay on location**



**IMG 04**  
**Bales of hay on location**





**IMG 05**

**Weeds beginning to encroach on produced water tank**



**IMG 06**

**Sound panels are unused**



**IMG 07**

**Berm height is diminished and impacted by animal burrows**