

Inspection Photos

July 11, 2022

Operator: Beeman Oil & Gas LLC - #7125

Location ID: 316756

Location Name: Routt Bonanza-67N87W /22SENE

Inspection Document #: 702800441

Moffat County, CO

SENE Section 22 T7N R87W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Routt Bonanza-67N87W /22SENE
Location ID: 316756



Photo 1. Photo taken from the Location entrance shows an overview of the southern portion of the Location.



Photo 2. Photo taken from the Location entrance shows an overview of the northern portion of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800441

Inspection Photos

Location Name: Routt Bonanza-67N87W /22SENE

Location ID: 316756



Photo 3. Photo taken at the north of the Location shows compromised tank battery secondary containment. Vegetation is growing throughout the secondary containment. Berms are eroded and appear poorly maintained. The liner is in disrepair. Red circle indicates houndstongue, a CO List B Noxious Weed.



Photo 4. Photo taken at the north of the Location shows compromised tank battery secondary containment. Vegetation is growing throughout the secondary containment. Berms are eroded and appear poorly maintained. Plants in the photo are common mullein, a CO List C Noxious Weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800441

Inspection Photos
Location Name: Routt Bonanza-67N87W /22SENE
Location ID: 316756



Photo 5. Photos show examples of stained soils present throughout the tank battery secondary containment. Red circle indicates Canada thistle, a CO List B Noxious Weed.



Inspection Photos

Location Name: Routt Bonanza-67N87W /22SENE

Location ID: 316756



Photo 6. Photos taken from the northeast of the Location shows stained soils below the separator equipment.

Inspection Photos
Location Name: Routt Bonanza-67N87W /22SENE
Location ID: 316756



Photo 7. Photo taken from the pumpjack shed shows stained soils at a pipe outlet. Red circle indicates Canada thistle, a CO List B Noxious Weed.



Photo 8. Photo taken in the pumpjack shed shows stained soils.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800441

Inspection Photos

Location Name: Routt Bonanza-67N87W /22SENE

Location ID: 316756



Photo 9. Photo taken from the east of the Location shows fluid dripping from a tank labelled as produced water.



Photo 10. Photo taken from the southeast of the Location shows vegetation growing around production equipment. Red circle indicates musk thistle, a CO List B Noxious Weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800441

Inspection Photos
Location Name: Routt Bonanza-67N87W /22SENE
Location ID: 316756



Photo 11. Photo taken at the pumpjack shows a chemical tote which appears to be unused equipment stored on Location.



Photo 12. Photo taken at the pumpjack shows barrels which appear to be unused equipment stored on Location.

Inspection Photos
Location Name: Routt Bonanza-67N87W /22SENE
Location ID: 316756



Photo 13. Photos show examples of debris/trash and/or equipment scattered throughout the Location.