

# Final Reclamation Inspection

July 13, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 336656

Inspection Document #: 697504059

Weld County, CO

NWSW Section 27 T5N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



**Photo 1.** Google Earth aerial imagery from 9/12/2018 during active operations. Photo illustrates the well location and the associated offsite tank battery.

Inspection Photos  
Location Name: UPRC #27-6C  
Location ID: 336656



**Photo 2.** Photo taken from the one TA well on location, facing East. Photo illustrates the Operator has plugged all other wells; therefore, this is a well release on an active location.



**Photo 3.** Photo taken of the associated offsite tank battery, facing West. Photo illustrates the Operator has removed all the equipment from the tank battery. The tank battery location is part of an active agricultural operation.