

# Inspection Photos and Issue Report

7/19/2022

Operator: LARAMIE ENERGY LLC # 10433

Location #334518

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location #334518



**Photo 1:** Photos taken from the cut slopes on the south end of the Location. Photo shows control measures to stabilize the soils are inadequate, and/or have not been maintained in proper functioning condition. Photo also shows reclamation work performed was inadequate; soils remain bare and exposed, with insufficient germination



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location #334518



**Photo 2:** See comments under photo 1.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location #334518



July 19, 2022



July 19, 2022

**Photo 2:** Interim areas not progressing towards 1003 uniform standards.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location #334518



**Photo 4:** Interim areas of the Location that are progressing towards 1003 standards.