

Inspection Photos
Location Name: Rotharmel 33A
Location ID: 309811



Photo 1: Tank Battery Sign



Photo 2: Gas meter not annually calibrated