

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 1: Wellhead Sign



Photo 2: Unused/disconnected equipment

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 3: Unused/disconnected equipment



Photo 4: Unused/disconnected equipment

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 5: Unused/disconnected equipment, stained soil



Photo 6: Stained soil

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 7: Unused/disconnected equipment



Photo 8: No wellhead sign

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 9: Unused/disconnected equipment



Photo 10: Unused/disconnected equipment

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 11: Unused/disconnected equipment



Photo 12: Unused/disconnected equipment

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528




Photo 13: Unused/disconnected equipment, stained soil



Photo 14: Unused/disconnected equipment, chemical storage

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 15: Unused/disconnected equipment



Photo 16: Unused/disconnected equipment

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 17: No wellhead sign



Photo 18: No wellhead sign

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 19: Unused/disconnected equipment



Photo 20: Stained soil

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 21: No wellhead sign



Photo 22: Unused/disconnected equipment

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 23: Unused/disconnected equipment



Photo 24: Unused/disconnected equipment

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 25: Unused/disconnected equipment



Photo 26: Weeds

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 27: Weeds



Photo 28: Weeds

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 29: Weeds



Photo 30: Debris

Inspection Photos
Location Name: Walt 25-D Pad
Location ID: 441528



Photo 31: Debris



Photo 32: Debris