

Inspection Photos

API: 125-06688

Operator: PETRON DEVELOPMENT COMPANY

Inspection Date: 7/21/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06688 | Date: 7/21/2022

Inspection Photos



Photo 1. Facing north toward the location. There is an area 30'x30' with no vegetation growth. This area has not been reclaimed. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06688 | Date: 7/21/2022

Inspection Photos



Photo 2. This bare area at the well site is was measured to be 30'x30' with insufficient vegetation growth. There are likely soil impacts preventing vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06688 | Date: 7/21/2022

Inspection Photos



Photo 3. Facing north toward the surrounding undisturbed CRP pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06688 | Date: 7/21/2022