

Inspection Photos

API: 125-09755

Operator: ENERGY QUEST II LLC

Inspection Date: 7/20/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 125-09755 | Date: 7/20/2022

Inspection Photos



Photo 1. Facing north toward the access road which has not been reclaimed. The access road should have been recontoured and reclaimed per 1004 Rules.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09755 | Date: 7/20/2022

Inspection Photos



Photo 2. There is oil and gas equipment that remains adjacent to the access road that must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09755 | Date: 7/20/2022

Inspection Photos



Photo 3. Facing north along the access road. There is erosion along the road which has not been reclaimed and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09755 | Date: 7/20/2022

Inspection Photos



Photo 4. Facing northeast along the access road. There is erosion along the road. The red arrow points to a 4 ft shovel for scale of erosion channel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09755 | Date: 7/20/2022

Inspection Photos



Photo 5. Facing northwest at the location. There is a perimeter fence around the location that is not maintained to prevent livestock entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09755 | Date: 7/20/2022

Inspection Photos



Photo 6. Facing northwest at the location. The desirable vegetation is sparse throughout the location and there are undesirable weeds (Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09755 | Date: 7/20/2022

Inspection Photos



Photo 7. Facing southeast at the location. The desirable vegetation is sparse throughout the location and there are undesirable weeds (Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09755 | Date: 7/20/2022

Inspection Photos



Photo 8. The fence around the location is in disrepair and barbed wire is stung out on the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09755 | Date: 7/20/2022

Inspection Photos



Photo 9. Facing north toward the surrounding undisturbed pasture consisting of Buffalo grass among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-09755 | Date: 7/20/2022